#### GOVERNMENT OF TELANGANA ABSTRACT

Minor Irrigation – Krishna Basin – "**Mission Kakatiya Phase-II**" "Comprehensive Restoration of 103 Minor Irrigation Tanks in Medak District for an amount of Rs. 3478.03 Lakhs – Administrative approval - Accorded – Orders - Issued.

\_\_\_\_\_\_

# **IRRIGATION & CAD (MI.T) DEPARTMENT**

G.O.RT.No. 377 Dated: 02/04/2016

Read:-

- 1. From the CE, MI (KB), Hyderabad Lr.No. DCE-I/OT1-AEE5/Mission Kakatiya-II/Medak/**List-XVII**/2016,Dt. 04.03.2016.
- 2. Government Memo. No. 2536/MI.T/A2/2016-2, Dt. 02-04-2016.

\*\*\*

#### ORDER:-

Government of Telangana has taken-up restoration of all Minor Irrigation Tanks in the State of their original capacity and to effectively utilize the 265.00 TMC of water allocated for Minor Irrigation sector under Godavari & Krishna River Basins as a flagship programme under the name of "MISSION KAKATIYA".

- 2. In the reference first read above, the Chief Engineer, Minor Irrigation (KB), Hyderabad has submitted proposal under Mission Kakatiya for "Comprehensive Restoration of 103 Minor Irrigation Tanks in Medak District for an amount of Rs. 3602.52 Lakhs, for according administrative approval.
- 3. Government after careful examination of the matter, hereby accord administrative approval for an amount of Rs. 3478.03 Lakhs (Rupees Thirty four crores seventy eight lakhs and three thousand only) towards "Comprehensive Restoration of 103 Minor Irrigation Tanks in Medak District" under Mission Kakatiya Phase-II for the Financial Year 2016-17 subject to meeting the expenditure from the available budget within the overall ceiling of the department, and to ensuring the following and the statement showing the details of tanks proposed for restoration is annexed to this order:
  - a) That the cost of repairs indicated against each tank is arrived after thorough investigation and as per the actual requirement of components and quantities for restoration and all the provisions made including L.S. Provisions if any are in terms of the codal provisions and the guidelines issued in relation thereto, and that the provisions made towards de-siltation in the estimates are based on the pre-levels and prudent assessment of quantities involved.
  - b) There is no overlap of proposed works under other sanctioned schemes and / or duplication.

- c) Pre entrustment procedure may be taken up during 2015-16 and ensure that expenditure of MK-Phase-II to be incurred during 2016-17 only.
- 4. The expenditure sanctioned in para (3) above shall be debited to the Head of Account "4702-00-101-11-23-530/531-O.E".
- 5. The Chief Engineer, Minor Irrigation (KB), Hyderabad, shall take necessary action accordingly, complete the work within the stipulated period and submit the utilization certificate to Government. The estimates received vide reference 1<sup>st</sup> read above are returned herewith and he is requested to acknowledge receipt of the same.
- 6. This order issues with the concurrence of Finance (EBS.IX) Department vide their U.O.No.3885/225/A2/EBS.IX/2016, Dated: 24.03.2016

## (BY ORDER AND IN THE NAME OF THE GOVERNOR OF TELANGANA)

#### S.K. JOSHI PRINCIPAL SECRETARY TO GOVERNMENT

To

The Chief Engineer, Minor Irrigation (KB), Hyderabad

## Copy to:-

The Dist. Collector, Medak District

The Finance (EBS.IX) Department.

The Accountant General, T.S. Hyderabad.

The Director of Works & Accounts, M.J. Market Road, T.S., Hyderabad.

PS to Hon'ble Minister (I. M, M&G and L A)

PS to Principal Secretary to Government, I & CAD Department.

PA to Joint Secretary to Government (T), I & CAD Department

The I & CAD (MI.G) Department

SF/SCs (C.No.2536/MI.T-A2/2016).

//forwarded by order //

**SECTION OFFICER** 

Continued	annexure
-----------	----------

ANNEXURE-I Medak District - List -XV

SI. No	unique I.D	Name of the Tank	Village	Mandal	Constituency	Longitude	Latitude	Ayacut	Cost for Repairs component Rs in Lakhs	Cost for Desiltation Rs in Lakhs	Total Cost of the estimate Rs in Lakhs
1	2	3	4	5	6	7	8	9	10	11	12
1	040424301101101	Pedda cheru	YAVAPUR	Tupran	Gajwel	78-30-53	17-49-17	213.00	83.36	16.14	99.50
2	040422100601502	Checkdam on Kudleru Vagu	BURRUGUPALLE	Gajwel	Gajwel	78-44-56	17-53-02	72.00	45.38	10.37	55.75
3	040424303001301	Kudi Kunta	JEEDIPALLE	Tupran	Gajwel	78-27-32	17-44-53	19.00	7.36	0.16	7.52
4	040411500501510	Check Dam near Lingala Balreddy feild a/c Nagaiah Vagu	MIRDODDI	Mirdoddi	Dubbak	78-40-20	18-04-46	62.00	32.98	0.00	32.98
5	040411501301309	Komati Kunta	ALWAL	Mirdoddi	Dubbak	78-40-10	18-02-16	43.00	13.09	1.65	14.74
6	040414601401501	Check Dam a/c Kudlair vagu near	ELIGADDAKISTAPUR	Thoguta	Dubbak	78-52-41	18-15-22	70.00	36.72	0.00	36.72
7	040414601401502	Check Dam a/c Kudlair vagu near	ELIGADDAKISTAPUR	Thoguta	Dubbak	78-10-05	17-51-10	95.00	24.80	0.00	24.80
8	040414600601311	Varda palloni kunta	LINGAPUR	Thoguta	Dubbak	78-39-39	17-59-21	28.00	10.28	7.11	17.39
9	040414601101304	Girmandari Kunta	P MASANPALLE / Pedda Masanpalle	Thoguta	Dubbak	78-05-21	18-05-52	22.00	10.35	0.00	10.35
10	040414600601313	Pandoni Kunta	LINGAPUR	Thoguta	Dubbak	78-42-21	17-56-47	22.00	7.78	0.00	7.78

SI. No	unique I.D	Name of the Tank	Village	Mandal	Constituency	Longitude	Latitude	Ayacut	Cost for Repairs component Rs in Lakhs	Cost for Desiltation Rs in Lakhs	Total Cost of the estimate Rs in Lakhs
1	2	3	4	5	6	7	8	9	10	11	12
11	040414600201305	Marmaloni Kunta /Malavoni kunta	ANDARUPALLE METTU H/o BANDARUPALLE	Thoguta	Dubbak	78-46-41	18-03-50	22.00	7.07	2.55	9.62
12	040414600601312	Kotha kunta (pasuloni kunta	LINGAPUR	Thoguta	Dubbak	78-43-0	18-0-38	22.00	11.68	0.00	11.68
13	040414600601310	Gokuloni Cheru/ Gokuloni kunta	LINGAPUR	Thoguta	Dubbak	78-39-54	17-59-51	35.00	25.16	1.79	26.95
14	040414601101313	Mangaloni Kunta	P MASANPALLE/Pedda Masanpalle	Thoguta Shankarampet	Dubbak	78-13-52	18-02-15	28.00	7.10	2.55	9.65
15	040341201501101	Pathacheruvu	SHANKARAMPETRURAL	[R]	Medak	78-22-41	18-02-30	237.00	65.12	4.55	69.67
16	040341200801102	Kudi Cheruvu	MADUR	Shankarampet [R]	Medak	78-23-15	18-01-20	106.00	43.67	11.05	54.72
17	040341202001102	Karam Cheruvu	DHARPALLE	Shankarampet [R]	Medak	78-21-50	17-57-40	131.00	53.55	11.11	64.66
18	040341201901201	Suraram Matadi	SURARAM	Shankarampet [R]	Medak	78-19-43	18-06-31	178.00	31.82	19.73	51.55
19	040341201901101	Reddy Cheruvu	SURARAM	Shankarampet [R]	Medak	78-24-21	17-57-24	147.00	51.11	12.04	63.15

SI. No	unique I.D	Name of the Tank	Village	Mandal	Constituency	Longitude	Latitude	Ayacut	Cost for Repairs component Rs in Lakhs	Cost for Desiltation Rs in Lakhs	Total Cost of the estimate Rs in Lakhs
1	2	3	4	5	6	7	8	9	10	11	12
20	040341202001101	Pedda Cheruvu	DHARPALLE	Shankarampet [R]	Medak	78-21-38	17-21-29	289.00	52.56	11.78	64.34
21	040341200501101	Pin cheruvu	MIRZAPALLE	Shankarampet [R]	Medak	78-24-35	18-01-17	113.00	47.00	11.53	58.53
22	040341201001101	Oora cheuvu	KORIVIPALLE	Shankarampet [R]	Medak	78-20-28	17-58-06	164.00	68.29	19.31	87.60
23	040412301101101	Upper cheru	UPPERPALLE	Chegunta	Dubbak	78-34-6	18-00-26	153.02	58.10	4.35	62.45
24	040412302101101	Ooracheru	WADIARAM	Chegunta	Dubbak	78-28-6	17-57-22	245.05	36.48	6.80	43.28
25	040412302201101	Ooracheru	CHINNA SHIVNOOR	Chegunta	Dubbak	78-27-59	17-58-27	246.04	41.97	6.33	48.30
26	040422101801404	THATTA KUNTA	PRAGNAPUR	Gajwel	Gajwel	78-40-27	17-48-36	15.00	7.10	1.73	8.83
27	040422101901301	Lingaraj cheru	MUTRAJPALLE	Gajwel	Gajwel	78-40-27	17-48-50	25.00	10.86	3.36	14.22
28	040424400601320	Medi Kunta	MYLARAM	Wargal	Gajwel	78-38-22	17-47-49	15.00	4.39	0.00	4.39
29	040424401601311	Kothakunta	VELURU	Wargal	Gajwel	78-32-25	17-46-38	24.00	6.57	2.08	8.65
30	040422001301307	Bramandlakunta	TEEGUL	Jagdevpur	Gajwel	78-47-52	17-52-12	15.00	4.80	0.00	4.80

SI. No	unique I.D	Name of the Tank	Village	Mandal	Constituency	Longitude	Latitude	Ayacut	Cost for Repairs component Rs in Lakhs	Cost for Desiltation Rs in Lakhs	Total Cost of the estimate Rs in Lakhs
1	2	3	4	5	6	7	8	9	10	11	12
31	040331801301503	Check dam a/c l/s Dharmasanogundi	ANKUSHAPUR	Nanganur	Siddipet	78-59-07	18-01-54	19.22	11.47	0.00	11.47
32	040331801201301	Eppalkunta	NARMETTA	Nanganur	Siddipet	78-57-39	18-03-34	38.14	21.33	2.36	23.69
33	040331800502307	Nemaligundu kunta	DARGAPALLE H/o BADDIPADAGA (V)	Nanganur	Siddipet	78-59-47	18-05-32	21.18	5.29	0.66	5.95
34	040331801601303	Thallakunta	GATLAMALLIAL	Nanganur	Siddipet	78-59-59	18-04-05	28.16	17.88	2.52	20.40
35	040331800101303	Yapala Kunta / Banjar Kunta	MUNDRAI	Nanganur	Siddipet	78-52-07	18-05-18	15.12	6.40	0.90	7.30
36	040331801403311	Oora kunta	SIDDANNAPET H/o NANGANUR (V)	Nanganur	Siddipet	78-45-52	18-25-48	18.10	7.55	0.00	7.55
37	040412300601306	Chakari kunta	IBRAHIMPUR	Chegunta	Dubbak	78-31-20	18-01-07	25.05	7.28	2.42	9.70
38	040412300801101	Ene cheru	PULAMAMIDI	Chegunta	Dubbak	78-29-27	18-01-05	148.20	34.97	8.15	43.12
39	040412300601101	Pedda Cheru	IBRAHIMPUR	Chegunta	Dubbak	78-31-4	18-10-39	292.35	51.22	5.25	56.47
40	040412302301310	Rayan cheru	MAKKARAJPET	Chegunta	Dubbak	78-30-14	17-57-48	51.20	10.01	1.14	11.15
41	040412302201306	Chetrai kunta	CHINNA SHIVNOOR (V)	Chegunta	Dubbak	78-29-48	17-57-16	21.05	11.49	1.28	12.77

SI. No	unique I.D	Name of the Tank	Village	Mandal	Constituency	Longitude	Latitude	Ayacut	Cost for Repairs component Rs in Lakhs	Cost for Desiltation Rs in Lakhs	Total Cost of the estimate Rs in Lakhs
1	2	3	4	5	6	7	8	9	10	11	12
42	040412301001101	Pedda Cheru	KONDAOPUR[BONAL]	Chegunta	Dubbak	78-33-03	18-02-40	357.17	63.78	10.77	74.55
43	040412302301101	Burugucheru	MAKKARAJPET	Chegunta	Dubbak	78-30-58	17-56-33	272.15	73.13	11.32	84.45
44	040412201002401	Kotha kunta	LINGAMPALLE H/o MOHAMADSHAPUR (V)	Doultabad	Dubbak	78-33-12	17-56-20	20.00	5.71	0.95	6.66
45	040412201401305	Pulicheru kunta	MANTOOR	Doultabad	Dubbak	78-39-7	17-58-17	34.00	11.73	1.29	13.02
46	040412202901303	Thalla kunta	YELKAL	Doultabad	Dubbak	78-35-19	17-51-17	15.00	9.50	1.90	11.40
47	040341201601302	Chinna Chervu	CHANDAMPET	Shankarampet [R]	Medak	78-25-39	17-57-51	112.00	37.26	12.34	49.60
48	040341201201101	Peddacheruvu	SHANKARAJ KONDAPUR	Shankarampet [R]	Medak	78-21-12	18-59-23	154.26	30.92	2.28	33.20
49	040341201001304	Devineni Kunta	KORIVIPALLE	Shankarampet [R]	Medak	18-00-04	78-22-40	20.00	14.20	2.85	17.05
50	040414601101311	Kummarolloni kunta	P MASANPALLE	Thoguta	Dubbak	78-13-50	18-00-28	20.00	6.60	2.55	9.15
51	040414600901303	Mothku Kunta	ZAPTHI LINGAREDDYPALL Y	Thoguta	Dubbak	78-42-04	18-01-18	26.00	14.02	2.55	16.57

SI. No	unique I.D	Name of the Tank	V ill	Mandal	Constituency	Longitude	Latitude	Ayacut	Cost for Repairs component Rs in Lakhs	Cost for Desiltation Rs in Lakhs	Total Cost of the estimate Rs in Lakhs
1	2	3	4	5	6	7	8	9	1	1	1
52	040414600201802	Peddi kunta	BANDARUPALLE METTU H/o BANDARUPALLE	Thoguta	Dubbak	78-46-57	18-02-45	26.00	8.22	2.55	10.77
53	040414600201302	Burugu kunta	BANDARUPALLE METTU H/o BANDARUPALLE	Thoguta	Dubbak	78-47-46	18-01-32	25.00	8.12	2.55	10.67
54	040414600901302	Mela Kunta	ZAPTHI LINGAREDDYPALLY	Thoguta	Dubbak	78-43-12	18-37-16	28.00	7.64	2.55	10.19
55	040414601101308	Karadi kunta	P MASANPALLE	Thoguta	Dubbak	78-12-15	18-02-52	23.00	12.57	3.18	15.75
56	040414600901305	Singai Kunta	ZAPTHI LINGAREDDYPALLY	Thoguta	Dubbak	78-41-19	18-00-49	29.00	9.95	2.55	12.50
57	040422100401501	Check dam on kudlaru	AHMADIPUR	Gajwel	Gajwel	78-50-12	17-48-26	60.00	14.75	4.40	19.15
58	040374103301101	Pallecheru	NAIMATULLAGUDA	Narsapur	Narsapur	78-17-44	17-41-24	100.00	47.70	8.61	56.31
59	040374100501101	Peddacheru	CHIPPALTURTHI	Narsapur	Narsapur	78-13-39	17-46-8	103.25	62.88	10.17	73.05
60	040341200801306	Rajuvani Kunta	MADUR	Shankarampet	Medak	78-23-00	18-02-46	25.00	20.67	3.23	23.90
61	040424501701302	Bandam cheroo	Narsampally	Mulugu	Gajwel	78-39-37	17-42-43	32.00	5.50	2.35	7.85
62	040422002401501	Ankilabai checkdam	Peeralapally	Jagdevpur	Gajwel	78-37-00	17-40-01	31.00	4.97	0.00	4.97
63	040414601301305	Gundla Kunta	Rampur	Thoguta	Dubbak	78-12-11	18-4-15	28.00	10.40	3.15	13.55

SI. No	unique I.D	Name of the Tank	V i I I a	Mandal	Constituency	Longitude	Latitude	Ayacut	Cost for Repairs component Rs in Lakhs	Cost for Desiltation Rs in Lakhs	Total Cost of the estimate Rs in Lakhs
1	2	3	4	5	6	7	8	9	1	1	1
64	040372401801305	Ragi kunta(Thaji kunta)	Ramanthapur	Yeldurthy	Narsapur	78-27-59	17-56-28	36.60	20.41	2.59	23.00
65	040374001501302	Nagireddy Kunta	Mangapur	Hatnoora	Narsapur	78-13-09	17-43-05	20.00	14.10	2.85	16.95
66	040424303401310	Thette Kunta	Rangaipally	Toopran	Gajwel	78-30-05	17-44-41	15.12	4.65	0.00	4.65
67	040341102801302	Devuni cheruvu	Thimanagar H/o MAGTA BHOOPATHIPUR	Medak	Medak	78-19-43	15053	30.00	21.52	3.88	25.40
68	040424401101411	Kadila kunta	Wargal	Wargal	Gajwel	78-38-13	17-45-35	16.00	3.97	1.96	5.93
69	040424500601802	Kalmera Kunta	TUNKIBOLLARAM H/O TUNIKI BOLLARAM	Mulug	Gajwel	78-35-25	17-45-30	18.00	5.64	1.14	6.78
70	040424500201309	Yerra kunta	KOKKONDA H/O KOKKONDA	Mulug	Gajwel	78-32-12	17-43-03	15.00	5.03	0.67	5.70
71	040424501202404	Nadimi kunta	BAVANANDAPUR H/O MARKOOK	Mulug	Gajwel	78-42-21	17-45-20	12.00	3.00	0.00	3.00
72	040424501904302	Gummadi Kunta	ANNASAGAR H/O CHILLA SAGAR	Mulug	Gajwel	78-37-58	17-41-20	20.00	5.31	1.59	6.90
73	040424501401312	Thimmayya kunta	KARKAPATLA H/O KARKAPATLA	Mulug	Gajwel	78-48-31	17-41-08	20.00	11.38	0.97	12.35

SI. No	unique I.D	Name of the Tank	Village	Mandal	Constituency	Longitude	Latitude	Ayacut	Cost for Repairs component	Cost for Desiltation Rs in	Total Cost of the estimate Rs in Lakhs
1	2	3	4	5	6	7	8	9	10	11	12
74	040424502101301	Nalla kunta	ZAPTHI SINGAIPALLE H/O ZAPTHI	Mulug	Gajwel	78-37-10	17-41-35	28.00	7.44	2.81	10.25
75	040414601302301	Bogamoni kunta	RAMPUR H/O THOGUTA	Thoguta	Dubbak	78-44-11	18-10-0	15.00	6.76	1.50	8.26
76	040414603101303	Kasai kunta	VARADARAJPALLY H/O Vardharajpally	Thoguta	Dubbak	78-44-8	18-04 16	45.00	18.54	1.81	20.35
77	040411401001302	Devathala Kunta	DUMPALAPALLE H/O DUMPALPALLY	Dubbak	Dubbak	78-41-26	18-09-52	48.00	23.37	4.28	27.65
78	040374102801101	Chowdarcheru	YELLAPUR	Narsapur	Narsapur	78-14-51	17-41-55	136.18	76.84	8.46	85.30
79	040374100301101	Peddacheru	ADMAPUR	Narsapur	Narsapur	78-12-23	17-42-2	140.00	64.19	9.66	73.85
80	040374100101101	Peddacheru	AHMEDNAGAR	Narsapur	Narsapur	78-12-23	17-49-4	144.00	50.48	10.53	61.01
81	040371000501302	Mallamchervu	RAMPUR	Kulcharam	Narsapur	78-13-24	17-59-31	15.00	11.41	0.70	12.11
82	040414601301310	Lingalavani Cheru	Rampur H/o THOGUTA (V)	Thoguta	Dubbak	78-22-10	18-43-12	90.00	16.03	7.93	23.96
83	040331601202307	Bandam Cheru	YELLUPALLU H/o MITTAPALLE	Siddipet	Siddipet	78-54-34	18-04-42	31.00	11.42	2.89	14.31
84	040424401101317	Ayyavari Kunta	WARGAL	Wargal	Gajwel	78-37-37	17-45-21	15.00	4.97	0.03	5.00
85	040422002601501	check dam a/c l/s	VARDARAJPUR	Jagdevpur	Gajwel	78-45-27	17-43-18	30.00	3.51	0.00	3.51

SI. No	unique I.D	Name of the Tank	Village	Mandal	Constituency	Longitude	Latitude	Ayacut	Cost for Repairs component Rs in Lakhs	Cost for Desiltation Rs in Lakhs	Total Cost of the estimate Rs in Lakhs
1	2	3	4	5	6	7	8	9	1	1	1
86	040341301401102	Somaiah Cheru	CHELMEDA	Ramayampet	Medak	78-29-50	18-8	169.31	102.64	23.57	126.21
87	040341302101101	Peddaraini Cheru	RAYALAPUR	Ramayampet	Medak	78-28-49	18-60	317.01	73.95	24.10	98.05
88	040412201601303	Reddy cheru	KOTHAPALLE	Doultabad	Dubbak	78-37-55	17-54-20	35.06	25.62	4.23	29.85
89	040331801201501	Check dam A/c L/sErravanikunta	NARMETTA	Nanganur	Siddipet	78-57-39	18-03-35	35.10	11.04	2.91	13.95
90	040393600801101	Mallam cheru	FASALWADI	Sangareddy	Medak	78-17-40	17-36-27	238.00	108.73	1.67	110.40
91	040393402501101	Maligiripet Vaagu	SURARAM	Sadasivpet	Sangaraddy	77-53-25	17-36-40	1560.00	198.29	82.81	281.10
92	040411401201404	Mala Kunta	HASAN MIRAPUR	Dubbak	Dubbak	78-42-59	18-10-29	31.25	7.43	4.80	12.23
93	'040414603201313	Maddi Kunta	Thoguta	GHANPUR	Dubbak	78-45-37	18-02 36	21.1	4.91	1.34	6.25
94	'040374001101104	Alvai cheru	Hathnoora	Hathnoora	Narsapur	78-11-17	17-44-22	108	64.24	21.31	85.55
95	040374002802301	Venkannagari Kunta	Yellammaguda	Hathnoora	Narsapur	78-15-11	17-40-08	20	15.58	1.32	16.90

SI N	unique I.D	Name of the Tank	<b>V</b> i I	Mandal	Constituenc y	Longitude	Latitude	Ayacut	Cost for Repairs component Rs in Lakhs	Cost for Desiltation Rs in Lakhs	Total Cost of the estimate Rs in Lakhs
1	2	3	4	5	6	7	8	9	1	1	11
96	040374000601101	Rayan cheru	Panyala	Hathnoora	Narsapur	78-08-11	17-45-25	110.6	64.54	24.58	89.12
97	040424502601101	Eedula cheru	Kothur	Mulug	Gajwel	78-31-51	17-42-38	136	50.28	14.12	64.40
98	040424500201101	Banda cheru	Kokkanda	Mulug	Gajwel	78-32-10	17-43-41	204	25.41	8.37	33.78
99	'040422102102301	Mallanna Kunta	Jaligon H/o Giripally	Gajwel	Gajwel	78-37-37	17-52-23	30	12.75	4.25	17.00
100	040374001001102	Ayyavari Cheru	Sikindlapur	Hathnoora	Narsapur	78-11-08	17-46-00	151	48.59	21.21	69.80
101	040412201201101	Nalla cheruvu	Raipole	Doulthabad	Dubbak	78-36-52	17-56-24	143.27	67.69	5.31	73.00
102	040412200402101	Pan cheruvu	Muthyampet H/o Surampally	Doulthabad	Dubbak	78-37-50	17-59-1	132.2	26.76	2.71	29.47
103	040414603501314	Kummari Kunta	Kangal	Thoguta	Medak	78-43-49	18-02 42	25.0	3.90	2.4	6.30
								9481.51	2873.93	604.10	3478.03

# S.K.JOSHI PRINCIPAL SECRETARY TO GOVERNMENT

//forwarded by order//

**SECTION OFFICER**